

# SINGATAC

ENGINEERING PTE LTD

YOUR 24X7 SOLUTION TO KEEP  
THE SHIPS SAFE & SAIL ON!

*We Make Things Happen!*

# Brief Profile

- 1997 : Singatac Engineering Pte Ltd was incorporated. Started a small outfit of less than 20 people and did basic sub-contract work in steel repair for ships in shipyards.
- 1998 : Rented a 4000ft<sup>2</sup> factory to carry out small scale fabrication for ship owners.
- 2000 : Upgraded & rented a 10,000ft<sup>2</sup> to fabricated bigger structures. Manpower increased to over 150 men.
- 2002 : Further upgraded & bought a 60,000ft<sup>2</sup> factory.
- 2005 : Added a seafront 100,000ft<sup>2</sup> yard.
- 2007 : Manpower increased to 600 men. Expanded overseas to Bintan, Indonesia.
- 2008 : Added another 120,000ft<sup>2</sup> rental factory space in Bintan, Indonesia.
- 2009 : Acquired a seafront yard of 700,000ft<sup>2</sup> in Bintan, Indonesia.
- 2011 : Brought in 2 dredgers to Bintan anchorage for 2-month refit.
- 2012 : Completed construction of 10m depth heavy duty wharf in the Bintan yard. Brought in the first heavy lift vessel alongside the yard. Downsized manpower in Singapore to 150 men. Upsized manpower in Bintan to 180 men.
- 2015 : Manpower in Bintan boosted to 500 men.

# Services



- Repair of hull damages due to collisions, mechanical contacts & corrosion
- Pipe fabrication & installation
- Fabrication, supply & installation of outfitting
- Repair, renewal & testing of machineries
- Cleaning & painting

# Typical Works Carried Out (1/4)



Deck Crane Repair



Propeller Repair



New Crane Column



New Gypsy Wheel



New End Covers



New Boiler Shell



Shipside Painting



Car Carrier Ramp door  
Repair

# Typical Works Carried Out (2/4)



Riding Crew on Voyage  
Repair



Anchor & Chain Renewal



Cell Guide Repair



New Crane Jib



In-Situ Crane Heel Pin Repair



Windlass Repair



Recovery of Lost Anchor  
Chain



Installation of Mooring  
Arrangement



# Typical Works Carried Out (3/4)



Pipe Fabrication



Pipe Installation



New Sighting Ports



Container Sockets Renewal



Rudder Repair



Steel Renewal



PBCF Installation



Steel Renewal

# Typical Works Carried Out (4/4)



Side Shell Renewal



Hatch Cover Repair



Damage Repair



Bow Damage Repair



Installation of Outriggers



Alongside Repair



Chain cleaning at OPL



Bollard Fabrication



# Facilities & Equipment & Manpower (1/2)

## □ Fully-Equipped Workshops



Bintan, Indonesia  
70,000m<sup>2</sup> yard c/w 200m waterfront  
for vessel upto LOA 200m & draft 8m  
(zero tide). Crane capacity up to 350  
ton.

Tuas, Singapore  
10,000m<sup>2</sup> yards c/w 100m waterfront  
for vessel upto LOA 100m & draft 2m (zero  
tide). Crane capacity up to 350 ton.





# Facilities, Equipment & Manpower (2/2)

- MANPOWER

Over 600 experienced and skilled employees in ship repairs including engineers, foremen, welders, fitters, riggers, scaffolders, painters, HSE officers, etc.

- CLASS-APPROVED WELDING PROCEDURES

Full range covering carbon steel (Y/S 275~690), pipes (API 5L Gr. A/B to X60), stainless steel (304/316), low-temp steel, aluminium, etc.

- EQUIPMENT

In-house precision machining, steel forming (1" rolling & 1000T pressing), CNC cutting, welding machines (SMAW, GMAW, GTAW, SAW), scaffolding, grit-blasting/spray painting equipment, 250T transporter, 50T~350T crawler cranes, cargo boat, crew boats, fenders, 18m-boomlifts, etc.


- QUALITY SYSTEM

All works will be carried in compliance with DNV-approved ISO 9000.

- SAFETY SYSTEM

All works will be carried in compliance with Singapore Ministry of Manpower's WSH Regulations and BizSafe Programme.

# Bintan Industrial Estate, Indonesia



A 4000-ha fully integrated industrial estate established since 1994. Major shareholders included Salim Group & Sembawang Group. Supported by Economic Development Board of Singapore under G2G initiative.

# Bintan Industrial Estate, Indonesia



Deck Crane Repair Alongside  
Singatag Wharf



Propeller Repair at Bintan IPL



Repair of Dredgers at Bintan  
IPL



Repair Alongside Singatag  
Wharf



Repair Alongside Singatag  
Wharf



Repair Alongside Singatag  
Wharf



# Bintan Industrial Estate, Indonesia



Repair at Bintan IPL



Repair at Bintan IPL



Alongside  
Singatac  
Wharf



Alongside  
Singatac  
Wharf

# Bintan Industrial Estate, Indonesia



Cold/Warm Stacking  
at Bintan IPL  
Anchorage, Indonesia

# Major Strengths

- Strong control of internal production resources, ie. manpower, equipment & facilities to provide 24x7 services.
- Very focus in the ship repair business, and we continue to reinvest into the business.
- Top-rate financial footing. We have zero debt.
- Dedicated, committed and highly professional team.
- Strategically ahead of competitors.
- Strong belief in getting the job done right.



# Contact Us

## SINGAPORE OFFICE:

No. 26 Tuas Avenue 10

Singapore 639147

Tel: (65) 68979566 Email: [info@singatac.com.sg](mailto:info@singatac.com.sg)

## BINTAN OFFICE:

Singatac Offshore Centre

Lot 2 Bintan Industrial Estate

Bintan, Kepulauan Riau 29154, Indonesia

Tel: (62) 770 696 788/789 Email: [soc@singatac.com.sg](mailto:soc@singatac.com.sg)

THE END. THANK YOU.